

Technical Bulletin

Product Information: Comfort I and Comfort II Controls

Operation Clarification

Please be aware of the following operation mode in the event of the power supply being interrupted to a Worcester appliance with a Comfort I RF or Comfort II RF control fitted.

The power supply could be interrupted for instance when a service intervention takes place.

After the power is restored to the appliance, if there is no interaction with the control, the system may not respond to a heating demand for up to 6 minutes whilst re-establishing the signal connection, this may lead to a misinterpretation of a fault occurring with the control system.

To re-establish the connection straight away and to check the operation of the control, increase the target temperature by way of turning the control knob on the front of the control unit. The boiler should respond to the demand in a short time. Remember to turn back to the original setting once all operational checks are complete.



Fig. 1) Comfort II controls



Fig. 2) Comfort I controls

Whilst it is always our intention to fully assist, it is essential to recognise that all information given by the company in response to an enquiry of any nature is provided in good faith and based upon the information provided with the enquiry. We recommend that advice should always be checked with your installer or contract partner. Consequently, the company cannot be held responsible for any liability relating to the use or repetition of such information or part thereof. In addition, whilst making every reasonable effort to monitor the performance and quality of our supply, installation and service network, we do not accept responsibility for the workmanship or operation of any third party company that the company may have promoted either in conversation, e-mail, or other communication. Similarly, the views and opinions expressed in communication with individuals within the company may not reflect that of the business as a whole.

You can find this, and all issued technical bulletins on the Worcester website at: www.worcester-bosch.co.uk/tb
or www.worcester-bosch.ie/tb